Item Quan/Bd Qty/PP Reference Part Description mfr part/stk number Ucost cost total QTY/PP Upgrade															
		2					per PP	10 t							
					Patch Panel Board Parts										
					103169-2 CONN HEADER VERT .100 8 POS										
1	16	32	J1-J16	CON8	30AU AMP/Tyco Electronics A26817-ND	\$0.77	\$24.64	320	\$246.40						
				00104	1-103168-5 CONN HEADER VERT .100	<b>**</b>	<b>*</b> 40.00		<b></b>						
2	4	8	J17-J20	CON34	34POS 30AU Digikey A26744-ND	\$2.37	\$18.96	80	\$189.60						
3	2	4	J21-J24	CON36	Connector 3M #10236-6212VC 36 pin MDR connector. 3M 10236-6212VC	\$2.80	\$11.20	40	\$112.00						
3		4	321-324	CONSO	ohm 200ppm SM RES-THICK FILM	Ψ2.00	ψ11.20	40	ψ112.00						
4	64	128	R1-R64	R0603	0603 5% 1/10W	\$0.0030	\$0.38	1280	\$3.84						
5	8	16	RN1-RN8	RN510-8	766163511G RES-NET ISO 510 OHM 16-PIN SMD CTS 766-163-R510-ND Digikey	\$0.24	\$3.78	160	\$37.76						
			141111410		Patch panel Printed circuit boards 2	Ψ0.2 :	ψοσ		φοιιισ						
6	1	2			layer 8 x 3x 0.062 Vendor	\$16.00	\$32.00	20	\$320.00						
7	1	2			Board assembly cost for patch panel	\$29.00	\$58.00	20	\$580.00						
	-					<b>V</b> =0.00	700.00		\$1,489.60						
															Total
					Purchase resolution proposal to						Money already		Future	Credits	obligations
					close out purchase order 564408						paid	obligations	obligations	negotiated	for 87 ATC
					Our cost incurred for bad patch panel boards manufacturing				\$1,489.60						
		55			Patch panel boards not assembled	\$5.33			\$293.15						
		- 00			i atempaner bearde net decembred	Ψ0.00			Ψ200.10						
					Bad patch panel boards and assembly				\$1,782.75		\$1,782.75				
										negotiated credit				-\$1,782.75	5
										D014474;prototype					
		25			original order of ATC cards				\$2,725.00		\$2,725.00				
		75			followup order of ATC cards				\$4,500.00	564408, production		\$4,500.00			
		75			lollowup order of ATC cards				\$4,500.00	layout		\$ <del>4</del> ,500.00			
										100 ordered plus					
										another 25 built. 25 prototype, 100					
										production received.					
										0 of 25 prototype					
										usable. 65 of 100					
										production usable. 35					
					Pentaplex cost incurred for bad ATC					of production run bad.					
		25			design our fault	\$60.00				Net 65 usable boards.		\$1,500.00			
										new order to be					
					boards needed to finish ATC with					placed to obtain required total of 87					
		22			spares total 87 needed.	\$60.00				usable boards.			\$1,320.00		
					Pentaplex has agreed to ship us the	ψ00.00			Ψ.,σ20.00				ψ.,σ2σ.σσ		
					22 boards only to bill us for an					JBG has negotiated a					
					additional 13 for a total of 90 on					credit against line 20					
		13			invoice. Current invoice is for 77	\$60.00			\$780.00	above.				-\$540.00	D
															\$4,997.25
										amount already in					φ <del>4</del> ,331.23
										MMS					\$4,500.00
										change req amount					\$497.25